



## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,808,612

DATED : October 26, 2004

INVENTOR(S) : Peter Hey, Byung-Sung Leo Kwak

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

**Page 2**

Foreign Patent Documents, add "DE 932 709".

**Column 11**

Line 59, add "a" after "into".

Line 63, change "20 mA\*sec/cm<sub>2</sub>" to "-20 mA\*sec/cm<sup>2</sup> -".

**Column 12**

Line 23, add "a" after "plating".

MAILING ADDRESS OF SENDER: B. Todd Patterson  
Moser, Patterson & Sheridan, L.L.P.  
3040 Post Oak Blvd., Suite 1500  
Houston, TX 77043

PATENT NO. 6.808.612

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

*If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.*